


QUICK START GUIDE





CONTROLS AND INDICATORS



Spare Battery



Insert a spare battery into the rear receptacle of the **HMC Handheld Dock**, with Contact Indicator (ORANGE Circle) pointing downwards to charge. This spare battery can be "hot swapped" when the external battery runs low, to extend the battery life of the HMC Handheld.





Install / Replace Battery



 Slide the battery door hatch to the unlocked position (Right)



When new HMC Handhelds are shipped, the battery compartment is empty.



2) If replacing battery, use PULL tab to remove the battery. If receiving a new HMC Handheld, insert battery. Remember to turn the battery so that the battery contacts align with the Contact Position indicator mark (ORANGE Circle)

Battery contacts in Android component



- 3) Insert the right edge of the battery into the battery pocket located in the battery door; then press the left edge of the battery into position.
 - *Never place the battery directly into the battery well. Installing the battery in this manner can damage the battery contacts in the HMC handheld.

NOTE: Observe the position of the Contact Position indicator mark (ORANGE Circle)

Dock Front



Power Indicator

HMC Handheld
Present and Connected
GREEN = Connected
RED = Not Connected

Spare Battery Charge Indicator

- Flashing GREEN Battery is actively charging
- Solid GREEN 3 Hr. Charge cycle complete

Ambient Light Sensor •

Controls the brightness of LEDs.

Dock Back



DC Power to Dock

- Diagnostic Port (factory use only)



Micro USB Port (Host/Client)

NOTE: Power can not be supplied to the dock via this port. However, power present on a connection to this port will not harm the device.

▲ Supplied 12VDC, 2A power supply